




PERSONAL PROTECTIVE EQUIPMENT (PPE)



Mexico Gas



Minimum PPE requirements when Flame Resistant (FR) clothing is required in Mexico Gas

Class E Type 2 Hard Hat

Gas detection is required in all areas where flame-resistant clothing and as required by the Portable Gas Detection Standard

FR is required when working near live gas systems. FR must be 8 cal/cm² and cover wrists down to ankles

Foot Protection must provide ankle support (i.e., approx. 6 in/15cm) and be puncture-resistant toed boots

Gloves are required based on the task being performed


Single or double hearing protection is required based on noise levels

Safety glasses or eye glasses with side shields

Wear clothing underneath FR that is primarily made of natural fibers such as tight-weave cotton

High visibility clothing selection is based on your site-specific hazard assessment and must be worn as the outermost garment

FR long sleeves are required under bib style coveralls



Before I don any of my PPE, I will always check to ensure it is in good condition because I know it's my last line of defense.

I will always complete a job risk and hazard assessment (i.e., JRHA, FLHA, JSA) to determine the right PPE for the job.

I will refer to the right procedures when working with electrical equipment requiring additional PPE.

I will don the appropriate respiratory protection equipment based on the hazards identified.

I will follow any additional Jurisdictional requirements for my working area that exceed PPE standard.

