



450 – 1 Street SW  
Calgary, Alberta T2P 5H1

Tel: (403) 920-7425  
Fax: (403) 920-2347  
Email: kenneth\_pountney@tcenergy.com

June 7, 2021

Filed Electronically

Canada Energy Regulator  
Suite 210, 517 Tenth Avenue SW  
Calgary, AB T2R 0A8

**Attention: Mr. Jean-Denis Charlebois, Secretary of the Commission**

Dear Mr. Charlebois:

**Re: NOVA Gas Transmission Ltd. (NGTL)  
Sundre Crossover (Project)  
Order XG-N081-030-2017 (Order)  
Condition 11: Updated Consultation Records  
File No.: OF-Fac-Gas-N081-2017-04 01**

In accordance with Condition 11 of the Order issued for the Project by the National Energy Board, predecessor to the Canada Energy Regulator (CER or Commission) on December 29, 2017, NGTL provides:

- Attachment 1: Updated Community Consultation Records
- Attachment 2: Updated Landowners – Traversed Consultation Records
- Attachment 3: Updated Landowners – Adjacent Consultation Records

These updates include Project-related engagement and consultation activities that occurred between November 16, 2020 and May 25, 2021. No Project engagement activities with Indigenous communities were conducted in this timeframe.

If additional information is required with respect to this filing, please contact me by phone at (403) 920-7425 or by email at kenneth\_pountney@tcenergy.com.

Yours truly,  
**NOVA Gas Transmission Ltd.**

*Original signed by*

Kenneth Pountney  
Regulatory Project Manager  
Regulatory Facilities, Canadian Natural Gas Pipelines

Enclosures

cc: Deborah Burgess, Canada Energy Regulator

---

Communication Date	Communication Summary	Stakeholders	Team Members	Communication Method
No engagement or consultation happened with the Community regarding the Sundre Crossover project during this period.				

Legal Land Description	Land Interest Type	Date	Consultation Summary
SW13-033-05W5M	Landowner	5/18/2021	NGTL spoke to the Landowner who mentioned that shavings and woodchips had been left behind. The Landowner asked NGTL to meet and discuss. When NGTL met the Landowner, they did not ask to have the woodchips removed.
		5/19/2021	The Landowner wanted to meet NGTL prior to the spring ROW assessment. The Landowner was happy with the work to date but mentioned some of the areas have heavier mulch and there is less vegetation growth.
NW12-033-05W5M	Landowner	5/18/2021	NGTL contacted the Landowner regarding the upcoming spring ROW assessment. The Landowner asked NGTL not to use all-terrain vehicles (ATVs) as the ROW was freshly seeded. Landowner said they fixed some subsidence on the ditch line as they were concerned it may sink further. NGTL said they would continue to monitor over the next two years.
		5/20/2021	NGTL called the Landowner to follow up with previous concerns regarding subsidence. The Landowner said they fixed the issues with the ditch line but remain concerned with possible future subsidence. NGTL said they would continue to monitor for two years and if subsidence resurfaces all necessary work would be done at that time to mitigate the issue.
SW12-033-05W5M	Landowner	5/19/2021	NGTL contacted the Landowner regarding the upcoming spring ROW assessment. The Landowner had no issues with using ATVs and did not mention any concerns with the ROW. The Landowner asked to only ride ATVs on the edge of the ROW if conditions are wet.
SE12-033-05W5M	Landowner	5/19/2021	NGTL contacted the Landowner regarding upcoming spring ROW assessments. The Landowner had no issues with the use of ATVs, but did indicate that some areas exhibited subsidence as well as foxtail growth on the ROW.
		5/25/2021	NGTL spoke to the Landowner regarding subsidence and foxtail concerns. The Landowner would like subsidence on ditch line filled with topsoil that they could provide. The Landowner also requested grass seed be spread on top and was good with having some spot spraying done when necessary.
NE01-033-05W5M	Landowner	5/21/2021	NGTL called the Landowner and left a voicemail. The Landowner called back and had no concerns with the ROW and use of ATVs.
SE01-033-05-W5M	Landowner	5/19/2021	The Landowner allowed NGTL to unload ATVs in the backyard because the gate has been removed where the ROW crosses Highway 27. The Landowner had no concerns with ROW.
NE36-032-05W5M	Landowner	5/19/2021	NGTL contacted the Landowner regarding the upcoming spring ROW assessments. The Landowner had no issues with the use of ATVs and did not mention any concerns with the ROW.
SE36-032-05W5M	Landowner	5/19/2021	NGTL contacted the Landowner regarding the upcoming spring ROW assessments. The Landowner had no issues with the use of ATVs and did not mention any concerns with ROW.
NE25-032-05W5M	Landowner	5/19/2021	NGTL contacted the Landowner and left a voicemail regarding the upcoming spring ROW assessment. NGTL was unable to get a hold of the Landowner, as such, crews walked the ROW.

Legal Land Description	Land Interest Type	Date	Consultation Summary
NW25-032-05W5M	Landowner	5/19/2021	NGTL contacted the Landowner regarding the upcoming spring ROW assessments. The Landowner had no issues with the use of ATVs and did not mention any concerns with ROW.
SW25-032-05W5M	Landowner	5/19/2021	NGTL contacted the Landowner regarding the upcoming spring ROW assessments. The Landowner had no issues with using ATVs and asked if NGTL would be looking at the alfalfa that was inter-seeded. NGTL confirmed they would be, the Landowner had no other concerns.
NW24-032-05W5M	Landowner	2/2/2021	NGTL received an email from the Landowner asking about the ROW reseeding as nothing is growing. NGTL advised the Landowner they would pass this onto the environmental monitoring team.
		2/17/2021	NGTL sent the Landowner an email advising them of the vegetation and weed control activities that took place on the ROW. The Landowner thanked NGTL for the response and advised they hope the ROW returns to normal.
		5/19/2021	NGTL sent text messages to the Landowner after a few missed calls. The Landowner called back and NGTL informed the Landowner of the spring ROW assessments. The Landowner said that no alfalfa has grown, NGTL said they would have a look and find a solution. No ATV access is allowed.
NE14-032-05W5M	Landowner	5/20/2021	NGTL contacted the Landowner regarding the upcoming spring ROW assessments. The Landowner mentioned lowlands holding water but had no other concerns.
SE14-032-05W5M	Landowner	5/20/2021	NGTL contacted the Landowner regarding the upcoming spring ROW assessments. The Landowner had concerns with low vegetation in a few areas and would like more growth on the ROW. The Landowner was okay with ATV access and had no other concerns.
SW13-032-05W5M	Landowner	5/21/2021	NGTL called the Landowner and left a voicemail. The ROW appeared to be in good condition at time of assessment.
NW12-032-05W5M BLOCK 1 PLAN 0512977	Landowner	2/24/2021	NGTL called the Landowner to advise them they have a new agreement to sign. The Landowner advised NGTL they can come anytime to sign. NGTL met with the Landowners to sign the agreement.
		3/31/2021	The Landowner called NGTL to inquire about the payment as they have not received it yet, NGTL advised they would inform the accounting department.
		4/14/2021	NGTL reached out to the Landowner to let them know that payment had been issued.
		5/21/2021	NGTL contacted the Landowner regarding the upcoming spring ROW assessments. The Landowner had no concerns with ATVs being used and asked NGTL to contact the occupant. NGTL was unable to reach the occupant, ROW looked to be in good condition at time of assessment.

Legal Land Description	Land Interest Type	Date	Consultation Summary
NE12-032-05W5M BLOCK 3 PLAN 9711075	Landowner	2/1/2021	NGTL contacted the Landowner via email providing an updated water monitoring report.
		4/29/2021	NGTL contacted the Landowner via email providing an updated water monitoring report.
		5/21/2021	NGTL contacted the Landowner regarding the upcoming spring ROW assessment. The Landowner had concerns with placement of a ditch plug and drainage tile on the ROW. The Landowner said if weeping tile could be out of the ground 50 m to the north it would allow use of that portion of the field and currently weeping tile is producing water preventing farming of the land.
SE12-032-05W5M	Landowner	5/25/2021	NGTL left a voicemail left.
		5/26/2021	NGTL spoke to the Landowner regarding the upcoming spring ROW assessment. The Landowner advised they would like the cross fence and temporary workspace (TWS) fencing removed. The Landowner further indicated that the north half of the quarter section was doing okay for vegetation, but south half looked sparse.
NE 01-032-05W5M	Landowner	5/4/2021	NGTL received a call from the Landowner asking about compensation for reseeding on the TWS and ROW as nothing has grown since they filled in the low spots. NGTL advised they would be in touch to sign off on the compensation.
		5/19/2021	NGTL sent damage releases to the Landowner to be executed for compensation.
		5/21/2021	NGTL tried calling the Landowner but there was no answer and NGTL was unable to leave a voicemail.
		5/26/2021	NGTL spoke with the Landowner regarding the upcoming spring ROW assessments. The Landowner was okay with crew accessing the ROW but did not want ATVs used.
NW01-032-05W5M	Landowner	5/7/2021	NGTL spoke with the Landowner regarding concerns with some bare spots on the ROW. The Landowner said he would like this addressed as soon as possible. NGTL said they would be in the area in 10 days and the Landowner requested to be contacted a day or two prior to meeting on site.
		5/19/2021	NGTL met with the Landowner regarding concerns with bare spots on the ROW. NGTL explained they give the vegetation some time to establish and positive trajectory has been reported in the past. The Landowner said they would like something done to the area lacking vegetation to encourage growth. NGTL and the Landowner walked the ROW and found the majority of bare areas lacking vegetation had woody debris present which could be inhibiting growth in these areas. NGTL told the Landowner they would do some additional seeding and clean up some of the woody debris where necessary. NGTL would also use soil amendments if necessary, in some areas to aid vegetation recovery. NGTL and the Landowner discussed cattle activity as it's contributing to the issue and the Landowner said they are willing to install electric fence any areas we repair to keep cattle out.

Legal Land Description	Land Interest Type	Date	Consultation Summary
NW36-031-05W5M	Landowner	5/25/2021	NGTL tried calling the Landowner but there was no answer and NGTL was unable to leave a message.
		5/26/2021	NGTL spoke to the Landowner regarding the upcoming spring ROW assessment. The Landowner had no concerns regarding the ROW and had no concerns with ATV access.
NW25-031-05W5M	Landowner	5/25/2021	NGTL contacted the Landowner regarding site assessment and they had no concerns. The Landowner advised NGTL to reach out to the occupant to discuss the assessments. NGTL spoke to the occupant who had no concerns and had no concerns with ATV access. Occupant asked to be contacted once site assessment was complete.
SW25-031-05W5M	Landowner	5/25/2021	NGTL spoke to the Landowner regarding site assessment and was okay with ATV access. The Landowner requested to be contacted once site assessment was complete.
NW24-031-05W5M LOT 1 BLOCK 1 PLAN 0411590	Landowner	5/25/2021	NGTL called the Landowner but there was no answer. NGTL called the occupant to discuss site assessment. Occupant had no issues with ATV access and discussed concerns with weak vegetation growth on the southeast corner. NGTL said they would follow up when the site assessment was complete.
SW24-031-05W5M	Landowner	5/25/2021	NGTL contacted the Landowner regarding site assessment. The Landowner had no issues with ATV access and requested that all gates be closed upon leaving and leave any open gates, open. The Landowner had questions regarding noxious weeds and herbicide applications. NGTL said they would conduct weed assessment and continue to monitor and communicate with the Landowner.

Land Interest Type	Date	Consultation Summary
Adjacent	2/1/2021	NGTL contacted the Landowner via email providing an updated water monitoring report.
	4/29/2021	NGTL contacted the Landowner via email providing an updated water monitoring report.